# Oil Field Environmental Incident Summary

Responsible Party: ONEOK

Well Operator: ONEOK ROCKIES MIDSTREAM

Well Name: Lignite gas plant

Field Name: Well File #:

Date Incident: 7/24/2014 Time Incident: 0900 Facility ID Number:

County: BURKE Twp: 162 Rng: 91 Sec: 7 Qtr: NW NW

Location Description: Lignite Gas Plant facility condensate tank battery

Submitted By: Kimberly Rudningen Received By:

Contact Person: Kim Rudningen

2700 Licnoln Ave SE Sidney, MT 59270

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 500 Feet

Distance Nearest Water Well: Type of Incident: Tank Leak

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

**Brine** 

Other 55 Gallons

**Description of Other Released Contaminant:** 

natural gas condensate/slop water

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

There are no immediate risks associated with this release

Areal Extent:

## Potential Environmental Impacts:

There are no environmental impacts from this release.

### Action Taken or Planned:

A consultant will be contacted to assist with delineation and remediation of this contaminated area. The area will be cleaned and remediated according to the consultants recommendations to the level required by the state of ND.

Wastes Disposal Location: A permitted landfill.

Agencies Involved:

### **Updates**

Date: 8/13/2014 Status: Reviewed - No Action Required Author: Roberts, Kris

Updated Oil Volume:

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

## Notes:

Small volume leak from a tank in secondary containment. No on-site inspection is necessary for this incident.